	Α	В	С	D	Е	F	G
1		201	3-14 Approved	d Facilities Repair/l	Renovation Projects R	equest	
2	Division	Project Name	Project Number	Department	Building	Floor and Room #	Repair/Renovation Request
F	Finance and Administration	Adams Roof	6061000492	2000.1	Adams House	1100111111	Roof Replacement
3		Replacemen					·
4	Student Affairs	Witmer IT Upgrade		Health Services	Witmer Infirmary		** Top indoor priority**3. New computer "wiring board" in basement to be able to add more computer equipment onto new electronic health system. Per IT/Electrician we are "maxed out" on space on present board for hard wired equipment.
5	Academic Affairs	Bassler HVAC	Combine	HSS - COMM	Bassler	Rm 122/121	Install HVAC Split System for Master Control or Bassler 121
6	Academic Affairs	Bassler HVAC	these two	HSS - COMM	Bassler	122	Add electrical capacity to Bassler Master Control
7	Academic Affairs	Remove this one; it is under \$5,000		HSS - HIST	McComsey	Rm 308	Assess Electrical and Network capacity to add instructional technology suite similar to those used in standard classrooms.
8	Academic Affairs	Roddy/Caputo Painting	6061000470	SCMA - None	Roddy & Caputo Hall	Exterior	Paint all exterior railings in the courtyard and surrounding Roddy & Caputo Halls.
9	Finance and Administration	Water Tower Repairs	Additional Info is being researched; the dollar is \$25k not \$200k	Facilities	Water Tower		5 year maintenance and improvements
10	Finance and Administration	Lyle Window Replaceme		Facilities	Lyle		Window replacement
11	Finance and Administration	Ware Center Roof Repai		Ware Center	Ware Center	Outside	Roof Repairs
12	Finance and Administration	Boyer Novar Upgrade		Facilities	Boyer		Novar control system upgrade
13	Academic Affairs	Breidenstine Paintin	6061000474	HSS - ART	Breidenstine	See Description	Art/ Breidenstine- Studios to be painted. The following studios have dirty and unsightly walls that need to be addressed: Sculpture (102,105, 109 and additional rooms where numbers are missing),
14	Finance and Administration	Wickersham Compressor		Facilities	Wickersham		Replace compressor A C no.1
15	Academic Affairs	Brooks AC-Heat		SoE	Brooks	Rm 41	AC-Heat Unit
	Finance and Administration	Chryst Need Cabinet Discussion- Chryst is owned by SSL	This property is owned by SL; Cabinet approved MU doing work	Facilities			
16	Finance and Administration	Lebanon AC		Facilities	Chryst Lebanon House		New air compressors and air handlers Replace air conditioning system 1st and
17	Finance and Administration	Upgrade Boyer Roddy		Facilities	Boyer Roddy		2nd floors Siemens Upgrade
18 19		Seimens Upgrade					
20	Auxiliary Funded						
	Finance and Administration	Gordinier Upper	Combine	Facilities	Gordinier		Roof Replacement Design
	Finance and Administration Finance and Administration	Deck	these three	Facilities Facilities	Gordinier Gordinier		Reconfiguration of Upper Deck replace Air Handlers
24	ano and Administration			. comico			